

Proposed Residential Development

Cleator Mills, Cumbria

Flood Risk Assessment



Reference	24294/FRADS/1
Client Name	Gleeson Regeneration
Date	May 2025
Version	7

CONTENTS

Confidentiality Statement

Document History

1.0 EXECUTIVE SUMMARY	4
2.0 INTRODUCTION	5
3.0 THE SITE.....	6
4.0 PROPOSED DEVELOPMENT	7
5.0 PLANNING POLICY AND CONSULTATION	8
6.0 FLOOD RISK.....	9
7.0 MANAGEMENT OF FLOOD RISK	15
8.0 CONSTRUCTION AND SURFACE WATER MANAGEMENT	16
9.0 CONCLUSIONS	17

APPENDICES

APPENDIX A:	SITE LOCATION PLAN
APPENDIX B:	TOPOGRAPHICAL SURVEY
APPENDIX C:	STRATEGIC FLOOD MAP
APPENDIX D:	EA FLOOD MAP RIVERS & SEA
APPENDIX E:	FLOOD ZONE OVERLAY
APPENDIX F:	FORMAL FLOOD DEFENCES PLAN
APPENDIX G:	FLOOD DEFENCE SURVEY
APPENDIX H:	UNITED UTILITIES GIS

CONFIDENTIALITY STATEMENT

This report is addressed to and may be relied upon by the following:

Stantec

This report has been prepared for the sole use and reliance of the above-named parties. This report shall not be relied upon or transferred to any other parties without the express written authorisation of RWO Group. No responsibility will be accepted where this report is used, either in its entirety or in part, by any other party.

This report includes an interpretation and assessment of data provided by third parties. Whilst every care has been taken to ensure that this information is accurate and up to date, RWO Ltd cannot guarantee the accuracy of third-party data.

The report findings and conclusions may be subject to change if this data is amended or updated after the consultation has taken place.

DOCUMENT HISTORY

VERSION	PURPOSE/DESCRIPTION	DATE
1	Draft Issue – for client comment	04.11.2020
2	Amended following Environment Agency comments	12.07.2021
3	Amended following addition flood modelling, LLFA & EA comments.	31.08.2022
4	Updated to suit the revised layout and unnamed watercourse flood modelling.	21.06.2023
5	Site developable area amended and risk assessed for new area.	28.11.2023
6	Modelling revised to consider both unnamed watercourse and River Ehen combined.	09.11.2024
7	Amended to suit latest Environment Agency Flood Maps	20.05.2025

1.0 EXECUTIVE SUMMARY

This assessment has looked at the implications of a proposed residential development in relation to flood risk and found all published risks to be low and/or manageable. The proposed developable site is in Flood Zone 1 & 2, placing the risk of flooding for the develop as low - medium.

As the developable area will be within Flood Zone 1 & 2, it meets with national standards for proposed residential dwellings.

To afford the dwellings protection it is proposed to raise the finished floor levels 600mm above the modelled flood level.

Other sources of flooding have been reviewed and deemed low and/or manageable.

Surface water during construction has been considered with interceptor drains included in the temporary state and the attenuation being constructed as the first element of the development site. constructed as the first element of the development site.

2.0 INTRODUCTION

RWO Associates Ltd (RWO) has been instructed by Gleeson Regeneration to prepare a Flood Risk Assessment to support a planning application for a proposed residential development at Cleator in Cumbria.

This assessment is reviewing the available information which includes;

- The Strategic Flood Risk Assessment.
- Environment Agency Flood Maps, published March 2025

This site is covered by a Strategic Flood Risk Assessment (by Jacobs dated 2007 and published on the local authority website [Strategic Flood Risk Assessment | Copeland Borough Council](#)) commissioned by Copeland Borough Council. This, more detailed, site-specific Flood Risk Assessment supplements the findings of the Strategic Flood Risk Assessment. It is also covered by the more recent Draft Copeland Borough Council, Level 1 SFRA. For clarity and reference purposes, this report has utilised the latest Draft SFRA dated 2018 to ensure the latest SFRA maps are utilised and considered as part of this FRA.

The site is currently Greenfield, and the client wishes to create residential development; location plans are included in Appendix A.

This report will review the risks associated with the River Ehen, the unnamed watercourse and other published risks. Recommendations as to the developable area and any mitigation requirements will also be made.

3.0 THE SITE

The proposed development site is located to the east of Cleator, about 300m to the south of Cleator Moor and immediately to the west of the Lake District National Park; Figure 1 below shows the site location. A site location plan is included in **Appendix B**.




Figure 1 – Site Location (Red line indicates the developable area)

The River Ehen forms the eastern and southern boundary, with residential dwellings located to the west and north. To the immediate south of the proposed development site is the former Kangol factory, with the building varying in age between the early 19th Century and the 1960s. The original building was a linen mill in the 19th Century. The eastern portion of the site historically had a derelict factory located on it, which has since been demolished, and it currently utilised as a Park & Ride. The A5086 is on the north-western boundary of the proposed development site.

A topographic survey of the site is provided in **Appendix B**.

4.0 PROPOSED DEVELOPMENT

It is proposed to consider the site for residential development and consider the number of dwellings that can be safely accommodated without increasing flood risk to others or creating a risk for the proposed development. Based upon the available information the extent of land ownership is located in Flood Zone 1, 2 & 3a, it is noted that the latest Environment Agency flood maps for planning identify the development site has flood defences located to the northeast and east. An extract of the strategic flood map can be seen below in Figure 2 (area identified as C14) with the full map included in **Appendix C**.



As the development site is shown as being located in Flood Zone 1, 2 and 3a with an annual probability of flooding of greater than 1:1000 year, between 1:100 and 1:1000 years and 1:100 years (>1%) , it will therefore be subject to the sequential and exception test in accordance with NPPF Technical Guidance should any development fall within flood zone 3a.

A topographical survey is included in Appendix B.

5.0 PLANNING POLICY AND CONSULTATION

PLANNING POLICY DOCUMENTS

The following planning policy documents were reviewed for this report:

- National Planning Policy Framework and Planning Practice Guidance 6 (2023)
- Flood And Water Management Act (April 2010)
- Defra Sustainable Drainage Systems Non-Statutory Technical Standards for Sustainable Drainage Systems (March 2015)
- Sustainable Drainage Systems Written Statement Hcws161 (2014)
- Environment Agency Flooding Maps
- Local Government Flooding Maps

SEQUENTIAL TEST

The proposed development has been sequentially planned such that all development will be limited to Flood Zone 1 & 2.

EXCEPTION TEST

As the proposed development is located in Flood Zone 1 & 2, the exception test is not required.

CONSULTATION

The following organisations data has been utilised to assess flood risk;

- Environment Agency (EA)
- Cumbria County Council (LLFA)
- United Utilities (UU)

Consultation responses have been received from all of the above organisations where appropriate.

COMPLIANCE

The scope of the Flood Risk Assessment has been developed based on all relevant policy information, along with requirements outlined in the consultation responses, with the latest response requesting the flood risk be reviewed following the latest flood maps be published.

It is therefore anticipated that this report fulfils the required criteria and is compliant with all relevant flood risk planning policy, subject to any further information being provided by the consultees.

6.0 FLOOD RISK

The site under consideration is located within Flood Zone 1, 2 & 3a on the latest version of the Indicative Floodplain Maps available on the Gov.uk website, a copy of the flood map is provided in **Appendix D**. The updated flood maps from the Environment Agency include the River Ehen and the unnamed watercourse to the North West. It should be noted it is only proposed to undertake development in Flood Zones 1 & 2, with all development being located outside of Flood Zone 3.

To assist with the clarity on the flood zones, the opensource flood maps have been downloaded and overlaid onto the OS Maps, a drawing is included in **Appendix E**. The areas located in flood Zones 1 & 2 will be developed with suitable raising of levels providing a 600mm freeboard over flood levels.

The site benefits from formal flood defences to the North East against flooding from the River Ehen, this affords the proposed developable area protection and along with raising of Finished Floor levels will ensure the development remains protected for all event up to and including the 1 in 1000-year return period. A plan showing the extent of formal flood defences is included in **Appendix F**. A copy of the flood defence survey is included in **Appendix G**.

The proposed site usage falls within the 'more vulnerable' category as identified in the NPPF Table 2: Flood Risk Vulnerability Classification. As such the exception test, will not need considering based on the NPPF Table 3: Flood risk vulnerability and flood zone 'compatibility'.

Flood Zones	Flood Risk Vulnerability Classification				
	Essential infrastructure	Highly vulnerable	More vulnerable	Less vulnerable	Water compatible
Zone 1	✓	✓	✓	✓	✓
Zone 2	✓	Exception Test required	✓	✓	✓
Zone 3a †	Exception Test required †	✗	Exception Test required	✓	✓
Zone 3b *	Exception Test required *	✗	✗	✗	✓*

Key:

✓ Development is appropriate

✗ Development should not be permitted.

Table 1 – 'NPPF Table 3: Flood Risk Vulnerability Classification'

Essential infrastructure • Essential transport infrastructure (including mass evacuation routes) which has to cross the area at risk. • Essential utility infrastructure which has to be located in a flood risk area for operational reasons, including electricity generating power stations and grid and primary substations; and water treatment works that need to remain operational in times of flood. • Wind Turbines.
Highly Vulnerable • Police stations, ambulance stations and fire stations and command centres and telecommunication installations required to be operational during flooding. • Emergency disposal points. • Basement dwellings. • Caravans, mobile homes and park homes intended for permanent residential use. • Installations requiring hazardous substances consent. (Where there is a demonstrable need to locate such installations for bulk storage of materials with port or other similar facilities, or such installations with energy infrastructure or carbon capture and storage installations, that require coastal or water-side locations, or need to be located in other high flood risk areas, in these instances the facilities should be classified as “essential infrastructure”).
More vulnerable • Hospitals. • Residential institutions such as residential care homes, children’s homes, social services homes, prisons and hostels. • Buildings used for dwelling houses, student halls of residence, drinking establishments, nightclubs and hotels. • Non-residential uses for health services, nurseries and educational establishments. • Landfill and sites used for waste management facilities for hazardous waste. • Sites used for holiday or short-let caravans and camping, <i>subject to a specific warning and evacuation plan.</i>
Less vulnerable • Police, ambulance and fire stations which are not required to be operational during flooding. • Buildings used for shops, financial, professional and other services, restaurants and cafes, hot food takeaways, offices, general industry, storage and distribution, non-residential institutions not included in “more vulnerable”, and assembly and leisure. • Land and buildings used for agricultural and forestry. • Waste treatment (except landfill and hazardous waste facilities). • Minerals workings and processing (except for sand and gravel working). • Water treatment works which do not need to remain operational during times of flood. • Sewerage treatment works (if adequate measures to control pollution and manage sewerage during flooding events are in place).
Water-compatible development • Flood control infrastructure. • Water transmission infrastructure and pumping stations.

- Sewage transmission infrastructure and pumping stations.
 - Sand and gravel working.
 - Docks, marinas and wharves.
 - Navigation facilities.
 - Ministry of defence installations.
- Ship building, repairing, dismantling, dockside fish processing and refrigeration and compatible activities requiring a waterside location.
 - Water based recreation (excluding sleeping accommodation).
 - Lifeguard and coastal stations.
- Amenity open space, nature conversation and biodiversity, outdoor sports and recreation and essential facilities such as changing rooms.
- Essential ancillary sleeping or residential accommodation for staff required by uses in this category, *subject to specific warning and evacuation plan.*

Table 2 – 'NPPF Table 2: Flood Risk Vulnerability Classification'

RWO have assessed the risk of flooding to the site from all known current and future potential.

The table below summarises the findings of the assessment. A more detailed explanation of the flood issues on the site and determination of flood risk ratings are presented in the below sections.

Flood Risk	
Risk of flooding from rivers and the sea	Low - Medium
Flood storage areas: part of floodplain	Not identified
Historical flood areas	Not identified
Areas benefiting from flood defences	Site
Flood defences	Existing
Proposed flood defences	Raising of levels to afford protection.
Surface water flood risk	Low
Groundwater flooding	Low
Sewer	As per GIS Plans

Modelled Flood Levels and Flood Depths

These have been requested and will be utilised to set the minimum finished floor levels across the developable area within existing flood zones 1 & 2.

Flood Warning Area

The site is not within or adjacent to a Flood Warning Area.

Tidal/Coastal Flood Risk

The site is not considered to be at risk from tidal flooding and sea level rise due to climate change is not expected to influence the site.

Groundwater Flooding

The EA information indicates that site is located within an area not considered to be at risk from groundwater flooding.

Reservoir Flooding

Reference to the Environment Agency information confirms that the site is outside of the zone of influence from any reservoir flooding.

Based on the available information, it is assessed that the site is at low risk of reservoir flooding.



Surface water

[More about your surface water flood risk](#)

Yearly chance of flooding

Very low

Low

Medium

High

Yearly chance of flooding between 2040 and 2060

Very low

Low

Medium

High

What surface water is

Surface water flooding is sometimes known as flash flooding. It happens when rainwater cannot drain away through normal drainage systems.

► [Why surface water flooding is a problem](#)

Other flood risks

[More about groundwater and reservoirs](#)

Groundwater

Flooding from groundwater is unlikely in this area.

Reservoirs

Flooding from reservoirs is unlikely in this area.

Figure 2 – EA Extract

Surface Water Flooding

The online Environment Agency surface water flood risk maps have been reviewed, and no areas within Flood Zone 1 7 2 are impacted by surface water flooding.

In summary the proposed development site is assessed to be at low risk from surface water flooding.




Figure 3 – EA Surface Water Extract

7.0 MANAGEMENT OF FLOOD RISK

Compensatory Flood Storage

The proposed development site is located in Flood Zone 1 & 2. Therefore, compensatory flood storage is not required.

Finished Floor Levels

Finished floor levels will be set a minimum of 600 mm the modelled flood levels to ensure adequate defence in the event of a flooding incident. External levels to be raised a minimum of 300mm above modelled flood levels.

Flood Resilience /Resistance

As it is proposed to raise finished floor levels to 600mm above the modelled flood levels, it is not deemed necessary to incorporate flood resilience measures.

Access and Egress

The extent of the flooding would not be considered to be sufficient enough to hinder emergency access/egress to the development site, in addition alternative access routes are available.

Design of External Surfaces and Infrastructure

The risk of surface water flooding to the site can be managed through the following.

- Engineering site levels to provide positive drainage away from buildings and other receptors, and towards the site drainage; and
- Construction of a suitably designed drainage system with adequate capacity and storage volume to manage surface water for events up to the 1 in 100-year design storm, including allowance for climate change.

8.0 CONSTRUCTION AND SURFACE WATER MANAGEMENT

To manage surface water during construction two processes are proposed.

- Interceptor drains with sumps constructed within each phase/parcel of development,

Interceptor drains will collect and capture overland flows once site topsoil strip has been undertaken and allow the flows to be conveyed to the existing drainage network. The interceptor drains will ensure that the overland flows are managed. Sumps will be formed at low points on the interceptor drains, and this will allow debris and potential pollutants to be captured.

An indicative surface water construction management drawing will be produced prior to construction.



9.0 CONCLUSIONS

This assessment has looked at the implications of a proposed residential development in relation to flood risk and found all published risks to be low and/or manageable. The proposed developable site is in Flood Zone 1 & 2, placing the risk of flooding for the develop as low - medium.

As the developable area will be within Flood Zone 1 & 2, it meets with national standards for proposed residential dwellings.

To afford the dwellings protection it is proposed to raise the finished floor levels 600mm above the modelled flood level.


Other sources of flooding have been reviewed and deemed low and/or manageable.

Surface water during construction has been considered with interceptor drains included in the temporary state and the attenuation being constructed as the first element of the development site.

RWO
May 2025



APPENDIX A: SITE LOCATION PLAN




Location Map	
Site	Cleator Mill - Residential
Client	Gleeson Regeneration
Job Number	19002
Scale	NTS



APPENDIX B: TOPOGRAPHICAL SURVEY



APPENDIX C: STRATEGIC FLOOD MAP



LEVEL 1 STRATEGIC FLOOD RISK ASSESSMENT

For
COPELAND BOROUGH COUNCIL

Please select a data type from the dropdown
menu below that you wish to view:

Flood Zones

- CBC boundary
- Detailed River Network
- LONP boundary
- Other LPA boundary

Potential Development Sites

- Employment Allocations
- Employment Opportunity
- Possible Housing Allocations
- Possible Opportunity Sites

New Sites Submitted 2


- Residential
- Employment
- Mixed Use
- Community Garden

- Flood Zone 3b
- Flood Zone 3a
- Flood Zone 2


☒ Show Site
Reference Labels




Contains public sector information licenced under the Open
Government Licence v3.0. Licence number 100019619





APPENDIX D: EA FLOOD MAP RIVERS & SEA



Environment Agency Flood Map	
Site	Cleator Mill – Residential
Client	Gleeson Regeneration
Job Number	19002
Scale	NTS



APPENDIX E: FLOOD ZONE OVERLAY



KEY

— SITE BOUNDARY

25/05/2025	LAYOUT OMITTED & BOUNDARY UPDATED TO RED AS REQUESTED	RM	RWO	2
10/05/2025	FIRST ISSUE	RM	AE	1
Date	Revisions	Drawn	Checked	Rev
Draw Status	SKETCH			
<				

GENERAL NOTES

- IN ACCORDANCE WITH THE CONSTRUCTION (DESIGN & MANAGEMENT) REGULATIONS 2015, IT IS THE POLICY OF THIS PRACTICE TO DESIGN OUT AS MANY IDENTIFIABLE RISKS AS POSSIBLE FOR THE CONSTRUCTION OPERATION AND MAINTENANCE OF THE PROJECT.
- ALL DRAWINGS ARE TO BE READ IN CONJUNCTION WITH THE PRE-CONSTRUCTION INFORMATION WHICH IS SUPPLIED BY THE CONSTRUCTION DESIGN & MANAGEMENT REGULATIONS 2015.
- A COMPETENT CONTRACTOR SHOULD BE AWARE OF NORMAL RISKS INVOLVED WITH THE CONSTRUCTION PROCESS. HOWEVER, ADDITIONAL PRECAUTIONS WILL NEED TO BE CONSIDERED FOR THE FOLLOWING ITEMS:
 - NONE IDENTIFIED.
 - NONE IDENTIFIED.
 - SAFETY METHODS AND SYSTEMS OF WORK REMAIN THE RESPONSIBILITY OF THE CONTRACTOR AND MUST BE IDENTIFIED IN THE CONSTRUCTION PHASE PLAN. THE CONSTRUCTION PHASE PLAN MUST BE IN PLACE FROM THE START OF ANY MODIFICATION TO ANY WORKS.
 - RESIDUAL RISKS THAT HAVE BEEN IDENTIFIED AND CANNOT BE DESIGNED OUT ARE AS FOLLOWS:
 - NONE IDENTIFIED.
 - IF ANY PARTY USING THE DRAWING CONSIDERS THAT THERE ARE 'ABNORMAL' RISKS THAT HAVE NOT BEEN IDENTIFIED ABOVE, THEN THE ENGINEER SHOULD BE NOTIFIED.

ADDITIONAL HEALTH & SAFETY NOTES


- CONTRACTOR SHOULD BE AWARE OF GENERAL CONSTRUCTION RISKS TO PREVENT SLIPS, TRIPS AND FALLS AND TAKE NECESSARY PRECAUTIONS WITHOUT SPECIAL INSTRUCTIONS.
- CONTRACTOR TO PROVIDE TRENCH SUPPORTS AS APPROPRIATE AND ENSURE THAT PLANT REMAINS A SAFE DISTANCE FROM TRENCHES PRIOR TO INSTALLING DRAINAGE.
- THE TIME THAT TRENCHES ARE OPEN ON SITE SHOULD BE KEPT TO A MINIMUM AND ALL TRENCHES SHOULD BE SURROUNDED BY A BARRIER.
- CONNECTIONS TO EXISTING SERVICES TO BE MADE BY APPROVED CONTRACTOR ONLY.
- CONTRACTOR TO MAKE OPERATIVES AWARE OF ASSOCIATED DANGERS TO HEALTH SUCH AS LEFT-HANDED JERKS, DISEASES AND RECOMMENDED PRECAUTIONS, ADEQUATE WELFARE FACILITIES AND PROTECTIVE CLOTHING TO BE PROVIDED AS REQUIRED.
- UNWEIGHTED MANHOLES MUST BE COVERED WITH LOAD-BEARING MATERIALS AND SURROUNDED WITH BARRIERS.
- PIPES & CABLES
- CONTRACTOR TO OBTAIN ALL SERVICES RECORDS PRIOR TO WORKS COMMENCING.
- SERVICE RECORDS TO BE REFERRED TO PRIOR TO WORK COMMENCING. CONTRACTOR TO PROCEED WITH CAUTION AND SERVICES TO BE LOCATED BY HAND AND PROTECTED ACCORDINGLY.

REGULATIONS


- CONTRACTOR TO ENSURE RELEVANT MEASURES ARE TAKEN TO KEEP PLANT AND PEOPLE A SAFE DISTANCE FROM STEEP SLOPES DURING THE WORKS.
- CONTRACTOR TO ENSURE THAT PROCEDURES ARE IN PLACE TO KEEP PEOPLE A SAFE DISTANCE FROM WORKING PLANT WHERE NECESSARY.
- CONTRACTOR TO REFER TO GEOTECHNICAL INVESTIGATION REPORT FOR CONTAMINATION TESTS AND TO PROVIDE ADEQUATE WELFARE FACILITIES AND PROTECTIVE CLOTHING AS REQUIRED.



APPENDIX F: FORMAL FLOOD DEFENCES PLAN



Environment Agency Flood Defence Map	
Site	Cleator Mill – Residential
Client	Gleeson Regeneration
Job Number	19002
Scale	NTS



APPENDIX G: FLOOD DEFENCE SURVEY



Cleator Flood Asset Condition Assessment

23 MAR 2022
Version 1.0
RAB: 2869



Disclaimer

This document has been prepared solely as a flood asset condition assessment report for RWO Group. RAB Consultants accepts no responsibility or liability for any use that is made of this document other than by the client for the purposes for which it was originally commissioned and prepared. No person other than the client may copy (in whole or in part) use or rely on the contents of this document, without the prior written permission of the Managing Director of RAB Consultants Ltd. Any advice, opinions, or recommendations within this document should be read and relied upon only in the context of the whole document.

Published by

RAB Consultants Limited
Second Floor
Cathedral House
Beacon Street
Lichfield
Staffordshire
WS13 7AA

Call: 01543 547 303

Email: enquiries@rabconsultants.co.uk

Visit: rabconsultants.co.uk

By viewing and saving this document digitally instead of printing it, you could save 4.6g of carbon emissions from double-sided printing on primary-sourced or 3.7g from 100% recycled A4 paper. Please only print this document if it is necessary.



Quality Control

Action	Name
Prepared	Alexandra Mackaness BSc (Hons)
Checked	Josh Spittle BSc (Hons) MSc
Approved	Peter Batty BEng (Hons) MSc GMICE

Revision History

Version	Date	Amendments	Issued to
1.0	23/03/2022		Ross Oakley



This page intentionally left blank.



Contents

1.0	INTRODUCTION	2
2.0	METHOD	2
3.0	FLOOD ASSETS AND CONDITION ASSESSMENT	3
4.0	FINDINGS AND RECOMMENDATIONS.....	6
	CL1 – Embankment	6
	CL2 – Natural High Ground.....	8
	CL3 – Wall	9
	CL4 – Outfall.....	10
	CL5 – Outfall.....	11
	CL6 – Wall	12
	CL7 – Outfall.....	13
	CL8 – Outfall.....	14
	CL9 – Outfall.....	15
	CL10 – Outfall.....	16
	CL11 – Outfall.....	17
	CL12 – Outfall.....	18
	CL13 – Natural High Ground.....	19
	CL14 – Engineered High Ground	20
	CL15 – Wall	21
	CL16 – Wall	22
	CL17 – Natural High Ground.....	23
	CL18 – Embankment	24
	CL19 – Outfall.....	26
	CL20 – Outfall.....	27
	CL21 – Embankment	28
	CL22 – Embankment	30
	CL23 – Outfall.....	32
	CL24 – Wall	33
5.0	SUMMARY COSTS OF REPAIR AND MAINTENANCE	34
6.0	SUMMARY	35
	APPENDIX A: ASSET INSPECTION LOGS.....	36



This page intentionally left blank



1.0 Introduction

Cleator, Cumbria is in the Borough of Copeland in the Northwest of England. The River Ehen is within the catchment of Copeland's Wild Rivers and runs from Ennerdale Water to Sellafield where it enters the Irish Sea. The watercourse passes through Cleator, where there are numerous flood defences and structures around the watercourse including embankments, outfalls, walls, natural high ground and engineered high ground.

Approximately 1km of the River Ehen flood assets were inspected to assess their condition, defects and required maintenance. This report contains details of the findings of these inspections including estimated costs for the preservation of the assets.

2.0 Method

The condition grading and descriptions given below are the standards adopted by the Environment Agency. The five condition grades range from 'very good' to 'very poor', and the descriptions reflect condition according to flood defence performance.

Grade	Rating	Description
1	Very Good	Cosmetic defects that will have no effect on performance
2	Good	Minor defects that will not reduce the overall performance of the asset
3	Fair	Defects that could reduce performance of the asset
4	Poor	Defects that would significantly reduce the performance of the asset. Further investigation needed
5	Very Poor	Severe defects resulting in complete performance failure

The inspection was carried out and recorded in accordance with the Condition Assessment Manual (March 2012) and Version 4 of the Asset Template and Weighting Guidance on 28 January 2022 by Environment Agency accredited Flood Asset Inspectors.

Visual inspection is the simplest form of non-destructive testing, as it does not require any specialist equipment. It is a widely used technique for monitoring assets and their surroundings. However, as only the surface of a structure is visible, this method can only assess the surface details and condition of an asset; changes to interior structure and condition are not easily identifiable until they lead to changes to the surface of the asset. Assessment of an asset's surroundings remains a key indicator to the asset's performance and integrity.

The recommendations arising from the visual inspection include remedial works to address visible defects and bring each element of the asset back to at least "fair" condition, but also actions to overcome access constraints and/or the need for other tests or investigations to assess an assets performance and integrity.



3.0 Flood Assets and Condition Assessment

Figure 1 and Table 1 provide a summary of the location, type and condition grade of flood assets identified and inspected on 28 January 2022.






TABLE 1: FLOOD ASSET CONDITION SUMMARY.

Asset ID	Asset type/sub-type	Description	Grade
CL1	Defence - Embankment	Embankment running in front of houses below Hilden Road and Kiln Brow	4
CL2	Defence – Natural High Ground	Natural high ground located below Hilden Road before wall	3
CL3	Defence – Wall	Stone wall on Hilden Road with berm	4
CL4	Structure – Outfall	Outfall located on River Ehen	3
CL5	Structure – Outfall	Outfall located on River Ehen	3
CL6	Defence – Wall	Stone wall on Hilden Road	4
CL7	Structure – Outfall	One of six identical outfalls located within wall on Hilden Road	2
C8	Structure – Outfall	One of six identical outfalls located within wall on Hilden Road	2
CL9	Structure – Outfall	One of six identical outfalls located within wall on Hilden Road	2
CL10	Structure – Outfall	One of six identical outfalls located within wall on Hilden Road	2
CL11	Structure – Outfall	One of six identical outfalls located within wall on Hilden Road	2
CL12	Structure – Outfall	One of six identical outfalls located within wall on Hilden Road	2
CL13	Defence – Natural High Ground	Natural high ground located below Mill Street	3
CL14	Defence – Engineered High Ground	Engineered high ground in front of old mill	3
CL15	Defence – Wall	Stone wall in front of old mill	3
CL16	Defence – Wall	Brick wall with brick channel side located on River Ehen	3
CL17	Defence – Natural High Ground	Natural high ground located on River Ehen	3
CL18	Defence – Embankment	Earth embankment located on River Ehen	3
CL19	Structure – Outfall	Drainage pipe located on River Ehen	3
CL20	Structure – Outfall	Outfall located on River Ehen	3
CL21	Defence - Embankment	Earth embankment with gabions and sheet piling on River Ehen	3



Asset ID	Asset type/sub-type	Description	Grade
CL22	Defence - Embankment	Earth embankment with stone and sheet piling on River Ehen	3
CL23	Structure – Outfall	Outfall located on River Ehen	3
CL24	Defence - Wall	Wall located off Main Street	3




4.0 Findings and Recommendations

The following is a summary of the findings and recommendations to bring all asset elements to at least “fair” condition, grade 3.

CL1 – Embankment

Small earth embankment protecting residential properties behind.



Comments

Variant weighting used for crest as <4m wide. Drainage pipe running through entire width of embankment, low spots, some animal holes and rutting on crest, landward face and exposed face have some holes and uneven slopes but are well vegetated. Undermining, minor erosion and light foreign objects present on channel side but currently stable.

Grade = 4, Poor

Years	Recommendations	Cumulative Cost (£)
Immediate	Install none return valve to drainage pipe	£400.00
1	- Inspect embankment annually and infill any identified low spots on crest with topsoil and lay down grass seed - Manage vegetation to avoid undesirable vegetation growth and maintain grass growth - Consider pest control	£600.00
5	- Continue to inspect the embankment yearly to keep track of and identify potential issues - Continue vegetation management to prevent the growth of undesirable vegetation on embankment	£3,500.00




	• Infill identified low spots on crest with topsoil and lay down grass seed • Monitor condition of landward toe to ensure vehicle use does not damage asset – infill low spots and lay down grass seed in areas of vegetation loss	
10	• Continue yearly inspections and vegetation management • If extensive damage has been incurred to the embankment, reprofile the bank and lay down grass seed	£12,500.00
15	• Continue yearly inspections and vegetation management • If extensive damage has been incurred to the embankment, reprofile the bank and lay down grass seed	£16,600.00



CL2 – Natural High Ground

Natural high ground located in a grass field in front of residential properties with a width of 21-48m between the channel side and road.



4.1.1 Comments

Significant undermining, erosion and presence of light foreign objects on channel side. High ground in good condition.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	Conduct visual asset inspections annually, monitor erosion, maintain grass on high ground and ensure vegetation is kept stable and not blocking channel	£600.00
5	- Continue to inspect the high ground yearly to keep track of and identify potential issues - Continue with vegetation management and remove unstable trees	£3,100.00
10	- Continue yearly inspections and vegetation management - If considerable amounts of erosion are being incurred to the channel side, install coir erosion protection matting	£13,200.00
15	- Continue yearly inspections and vegetation management - If extensive erosion has been incurred to the channel side, consider reprofiling bank and installing rock armour	£21,500.00



CL3 – Wall

Stone wall next to road protecting residential properties but not designed as a flood wall.



4.1.2 Comments

Variant weightings used for both faces as no revetments. Significant mortar loss to crest, holes through wall, bulging of wall where light foreign objects are growing in front on wall, distorting its shape and some erosion to channel side.


Grade = 4, Poor

Years	Recommendations	Cumulative Cost (£)
Immediate	Rebuild wall and remove trees in front of wall	£1,900.00
1	- Conduct visual asset inspections annually - Carry out minor repairs to bricks and mortar and maintain grass on berm	£200.00
5	- Continue to inspect the wall yearly to keep track of and identify potential issues - Carry out small repairs to brickwork and management of surrounding vegetation	£1,000.00
10	- Carry out repointing of wall - Continue with annual visual asset inspections and management of surrounding vegetation	£2,100.00
15	- If there has been any serious structural damage to the wall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage - If extensive erosion has been incurred to the channel side, consider reprofiling bank and installing rock armour	£10,100.00



CL4 – Outfall

300mm diameter flapped outfall with concrete apron located on channel side in front of wall. Owner and operator unknown.



4.1.3 Comments

Vegetation around headwall. Unable to see through pipe and no CCTV footage available.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	Conduct annual visual asset inspections and maintain surrounding vegetation to avoid damage incurring to outfall	£600.00
5	- Continue to inspect the outfall yearly, including CCTV inspections of the pipe every 5 years - Monitor and remove moss growth and vegetation growth on headwall to reduce damage to the headwall	£3,500.00
10	- Continue yearly inspections of outfall including CCTV inspections of pipe every 5 years - Continue with vegetation management - Carry out small repairs to brick and mortar loss	£6,900.00
15	- Continue yearly inspections of outfall and manage vegetation growth - If there has been any serious structural damage to the outfall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ relevant operative to repair damage	£17,400.00



CL5 – Outfall

300mm diameter flapped outfall with no apron located on channel side in front of wall. Owner and operator unknown.



4.1.4 Comments

Outfall in good condition, very minor corrosion present on frame and flap valve. Unable to see through pipe and no CCTV footage available.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	Conduct annual visual asset inspections and maintain surrounding vegetation to avoid damage incurring to outfall	£600.00
5	- Continue to inspect the outfall yearly, including CCTV inspections of the pipe every 5 years - Monitor and remove moss growth and vegetation growth on headwall to reduce damage to the headwall	£3,500.00
10	- Continue yearly inspections of the outfall including CCTV inspections of the pipe every 5 years - Continue with vegetation management	£6,900.00
15	- Continue yearly inspections of the outfall and manage vegetation growth - If there has been any serious structural damage to the outfall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£17,400.00



CL6 – Wall

Stone wall with 6 highway outfalls in wall connecting to previous wall, also not a flood wall.



4.1.5 Comments

Heavy foreign objects growing towards channel on berm and channel side and undermining on channel side causing channel side to be unstable. Ivy growth on wall, heavy foreign objects growing close to wall causing bulging to wall and capping stones lost from crest halfway across wall.


Grade = 4, Poor

Years	Recommendations	Cumulative Cost (£)
Immediate	Rebuild wall, remove unstable trees, and remove trees next to wall	£5,000.00
1	- Conduct visual asset inspections annually - Maintain surrounding vegetation to avoid wall incurring structural damage	£200.00
5	- Continue to inspect the wall yearly to keep track of and identify potential issues - Small repairs to brickwork and management of surrounding vegetation	£1,000.00
10	Carry out repointing of wall and continue with small repairs to brickwork and management of surrounding vegetation	£2,100.00
15	- If there has been any serious structural damage to the wall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage - If extensive erosion has been incurred to the channel side, consider reprofiling bank and installing rock armour	£11,000



CL7 – Outfall

110mm diameter flapped highway outfall located within stone wall.



4.1.6 Comments

No signs of corrosion to flap valve or frame, pipe has minor leaf debris but no blockages or damage. Downstream headwall has some cracks, vegetation growth and mortar loss.


Grade = 2, Good

Years	Recommendations	Cumulative Cost (£)
1	Conduct annual visual asset inspections and maintain surrounding vegetation to avoid damage incurring to outfall	£600.00
5	- Continue with annual inspections of the outfall - Monitor and remove moss growth and vegetation growth on headwall to reduce damage to the headwall	£3,500.00
10	- Continue with annual inspections of the outfall - Continue with vegetation management - Conduct small brick and mortar repairs on headwall	£6,900.00
15	- Continue with annual inspections of the outfall and vegetation management - If there has been any serious structural damage to the outfall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£14,800.00



CL8 – Outfall

110mm diameter flapped highway outfall located within stone wall.



4.1.7 Comments

No signs of corrosion to flap valve or frame, pipe has minor leaf debris but no blockages or damage. Minor crack to downstream headwall, vegetation growth and mortar loss.


Grade = 2, Good

Years	Recommendations	Cumulative Cost (£)
1	Conduct annual visual asset inspections and maintain surrounding vegetation to avoid damage incurring to outfall	£600.00
5	- Continue with annual inspections of the outfall - Monitor and remove moss growth and vegetation growth on headwall to reduce damage to the headwall	£3,500.00
10	- Continue with annual inspections of the outfall - Continue with vegetation management - Conduct small brick and mortar repairs on headwall	£6,900.00
15	- Continue with annual inspections of the outfall and vegetation management - If there has been any serious structural damage to the outfall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£14,800.00



CL9 – Outfall

110mm diameter flapped highway outfall located within stone wall.



4.1.8 Comments

No corrosion to flap valve or frame. Cracks and mortar loss on headwall. Pipe has minor leaf debris but no blockages or damage.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	Conduct annual visual asset inspections and maintain surrounding vegetation to avoid damage incurring to outfall	£600.00
5	- Continue with annual inspections of the outfall - Monitor and remove moss growth and vegetation growth on headwall to reduce damage to the headwall	£3,500.00
10	- Continue with annual inspections of the outfall - Continue with vegetation management - Conduct small brick and mortar repairs on headwall	£6,900.00
15	- Continue with annual inspections of the outfall and vegetation management - If there has been any serious structural damage to the outfall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£14,800.00



CL10 – Outfall

110mm diameter flapped highway outfall located within stone wall.



4.1.9 Comments

Ivy growth around frame and headwall. No corrosion to flap valve. Minor cracks and vegetation growth on headwall. Pipe has minor leaf debris but no blockages or damage.


Grade = 2, Good

Years	Recommendations	Cumulative Cost (£)
1	Conduct annual visual asset inspections and maintain surrounding vegetation to avoid damage incurring to outfall	£600.00
5	- Continue with annual inspections of the outfall - Monitor and remove moss growth and vegetation growth on headwall to reduce damage to the headwall	£3,500.00
10	- Continue with annual inspections of the outfall - Continue with vegetation management - Conduct small brick and mortar repairs on headwall	£6,900.00
15	- Continue with annual inspections of the outfall and vegetation management - If there has been any serious structural damage to the outfall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£14,800.00



CL11 – Outfall

110mm diameter flapped highway outfall located within stone wall.



4.1.10 Comments

Ivy growth around frame and headwall. No corrosion to flap valve. Minor cracks and vegetation growth on headwall. Pipe has vegetation debris but no blockages or damage.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	Conduct annual visual asset inspections and maintain surrounding vegetation to avoid damage incurring to outfall	£600.00
5	- Continue with annual inspections of the outfall - Monitor and remove moss growth and vegetation growth on headwall to reduce damage to the headwall	£3,500.00
10	- Continue with annual inspections of the outfall - Continue with vegetation management - Conduct small brick and mortar repairs on headwall	£6,900.00
15	- Continue with annual inspections of the outfall and vegetation management - If there has been any serious structural damage to the outfall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£14,800.00



CL12 – Outfall

110mm diameter flapped highway outfall located within stone wall.



4.1.11 Comments

No corrosion to flap valve or frame. Minor cracks, mortar loss and minor vegetation growth on headwall. Pipe has minor leaf debris but no blockages or damage.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	Conduct annual visual asset inspections and maintain surrounding vegetation to avoid damage incurring to outfall	£600.00
5	- Continue with annual inspections of the outfall - Monitor and remove moss growth and vegetation growth on headwall to reduce damage to the headwall	£3,500.00
10	- Continue with annual inspections of the outfall - Continue with vegetation management - Conduct small brick and mortar repairs on headwall	£6,900.00
15	- Continue with annual inspections of the outfall and vegetation management - If there has been any serious structural damage to the outfall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£14,800.00



CL13 – Natural High Ground

Stretch of natural high ground with vegetation and trees.



4.1.12 Comments

Significant undermining, erosion, and presence of light foreign objects on channel side. High ground in good condition.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	Conduct visual asset inspections annually, monitor erosion and ensure vegetation is kept stable and not blocking channel	£700.00
5	- Continue to inspect high ground yearly to keep track of and identify potential issues - Continue with vegetation management and remove unstable trees	£5,500.00
10	- Continue yearly inspections and vegetation management - If considerable amounts of erosion are being incurred to the channel side, install erosion protection matting	£17,900.00
15	- Continue yearly inspections and vegetation management - If extensive erosion has been incurred to the channel side, consider reprofiling bank and installing further erosion protection measures such as rock armour	£34,200.00



CL14 – Engineered High Ground

Masonry retaining wall at edge of road with metal fencing above.



~20m in length

4.1.13 Comments

Light foreign objects and ivy growing in front of and on top of channel side wall. High ground is road in good condition. Heavy foreign object upstream with roots growing into channel side brickwork.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	Conduct visual asset inspections annually and cut back surrounding vegetation to avoid damaging asset	£600.00
5	- Continue with annual visual asset inspections and vegetation management - Conduct small brick and mortar repairs	£1,100.00
10	- Continue with annual visual asset inspections and vegetation management - Consider repointing brickwork	£2,200.00
15	- Continue with annual visual asset inspections and vegetation management - If there has been any serious structural damage to the engineered high ground such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£12,000.00



CL15 – Wall

Masonry wall with capping stones with berm and channel side heavily vegetated with tree growth through wall.



4.1.14 Comments

Several heavy foreign objects on berm and channel side. Severe mortar loss in landward face, exposed face difficult to inspect but wall covered in ivy and some tree roots and growing through it. Crest is uneven where ivy has grown around it.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	- Conduct visual asset inspections annually - Maintain surrounding vegetation including ivy removal to avoid wall incurring structural damage	£200.00
5	- Continue to inspect the wall yearly to keep track of and identify potential issues - Small repairs to brickwork and management of surrounding vegetation	£1,200.00
10	Carry out repointing of wall and continue with small repairs to brickwork and management of surrounding vegetation	£2,400.00
15	If there has been any serious structural damage to the wall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£7,700.00



CL16 – Wall

Brick wall with concrete landward face connecting to channel side brick retaining wall.



~30m in length

4.1.15 Comments

Extensive ivy growth, channel side wall is walling down with severe brick loss and root penetration. Heavy foreign objects growing on channel side causing brick displacement and loss. Crest is uneven due to brick loss but landward face is made from concrete slabs in good condition.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	- Conduct visual asset inspections annually - Maintain surrounding vegetation to avoid wall incurring structural damage	£200.00
5	- Continue to inspect the wall yearly to keep track of and identify potential issues - Small repairs to brickwork and management of surrounding vegetation	£1,200.00
10	Carry out repointing of wall and continue with small repairs to brickwork and management of surrounding vegetation	£4,800.00
15	If there has been any serious structural damage to the wall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£8,200.00



CL17 – Natural High Ground

Natural high ground heavily vegetated with tree growth with brick building directly behind.



4.1.16 Comments

Heavy foreign objects on channel side leaning towards channel. Building <3m from channel on high ground.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	- Remove unstable trees - Conduct visual asset inspections annually, monitor erosion and movement which could affect nearby building - Ensure vegetation is kept stable and not blocking channel	£200.00
5	- Continue to inspect high ground yearly to keep track of and identify potential issues - Continue with vegetation management and remove unstable trees	£1,200.00
10	- Continue yearly inspections and vegetation management - If considerable amounts of erosion are being incurred to the channel side, install coir erosion protection matting	£4,800.00
15	- Continue yearly inspections and vegetation management - If extensive erosion has been incurred to the channel side, consider reprofiling bank and installing further erosion protection measures such as rock armour	£8,200.00



CL18 – Embankment

Earth embankment with unknown construction materials and unstable tree-ridden channel side, reducing stability of embankment. Unlikely to have clay core and may be comprised of waste material.



4.1.17 Comments

Low points and rutting in crest but well vegetated. Variant used for exposed face due to steepness. Exposed and landward faces have isolated bare patches. Telegraph pole behind embankment but embankment build around it. Severe undermining of channel side around heavy foreign objects with extensive root exposure.

Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	- Consider installing erosion protection to channel side such as rock armour - Inspect embankment annually and infill any identified low spots on crest with topsoil and lay down grass seed - Manage vegetation to avoid undesirable vegetation growth	£7,200.00
5	Continue to inspect the embankment yearly to keep track of, identify potential issues and monitor stability of telegraph pole within embankment	£33,400.00




	• Continue vegetation management to prevent the growth of undesirable vegetation on embankment • Infill identified low spots on crest with topsoil and lay down grass seed	
10	• Continue yearly inspections and vegetation management • Infill any identified low spots on crest with topsoil and lay down grass seed • If extensive damage has been incurred to embankment, reprofile bank and lay down grass seed	£90,100.00
15	• Continue yearly inspections and vegetation management • Infill any identified low spots on crest with topsoil and lay down grass seed • If extensive damage has been incurred to embankment, reprofile bank and lay down grass seed • Consider employing engineer to assess asset condition in detail to identify potential structural issues with embankment, employ relevant operative to repair damage	£166,600.00



CL19 – Outfall

300mm outfall on channel side of embankment with damaged concrete headwall.



4.1.18 Comments

Drainage pipe halfway between wall and building on high ground. Unable to see through pipe and no CCTV footage available. Vegetation around headwall and at base of pipe.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	- Investigate stability of headwall, rebuild if necessary - Conduct CCTV inspection of pipe to assess condition - Conduct annual visual asset inspections and provide ongoing management of surrounding vegetation to avoid damage incurring to outfall	£600.00
5	- Continue to inspect the outfall yearly, including CCTV inspections of the pipe every 5 years - Monitor and remove moss growth and vegetation growth on headwall to reduce damage to the headwall - Carry out small repairs to any brick and mortar loss on headwall	£3,500.00
10	- Continue yearly inspections of outfall including CCTV inspections of pipe every 5 years - Continue with vegetation management - Carry out small repairs to any brick and mortar loss on headwall	£6,900.00
15	- Continue yearly inspections of outfall and manage vegetation growth - If there has been any serious structural damage to the outfall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ relevant operative to repair damage	£17,400.00



CL20 – Outfall

150mm clay drainage pipe located on channel side of embankment surrounded by rocks providing unstable headwall.



4.1.19 Comments

Downstream headwall in pieces. Unable to see through pipe and no CCTV footage available.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	- Rebuild headwall - Conduct CCTV inspection of pipe to assess condition - Conduct annual visual asset inspections and provide ongoing management of surrounding vegetation to avoid damage incurring to outfall	£600.00
5	- Continue to inspect the outfall yearly, including CCTV inspections of the pipe every 5 years - Monitor and remove moss growth and vegetation growth on headwall to reduce damage to the headwall - Carry out small repairs to any brick and mortar loss on headwall	£3,500.00
10	- Continue yearly inspections of outfall including CCTV inspections of pipe every 5 years - Continue with vegetation management - Carry out small repairs to any brick and mortar loss on headwall	£6,900.00
15	- Continue yearly inspections of outfall and manage vegetation growth - If there has been any serious structural damage to the outfall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ relevant operative to repair damage	£17,400.00



CL21 – Embankment

Earth embankment with gabion basket and sheet piling exposed faces and concrete berm.



4.1.20 Comments

Berm 2 and channel side in good condition with minor cosmetic defects to sheet piles. Vegetation growth through gabion baskets with a few broken wires but no gabion displacement. Uneven ground on exposed face 1 and landward face but well vegetated. Rutting and low spots in isolated places on crest. Variants used on crest as less than 4m wide and landward face due to steepness.

Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	- Repair gabion baskets and remove vegetation growing through - Inspect embankment annually and infill any identified low spots on crest with topsoil and lay down grass seed - Manage vegetation to avoid undesirable vegetation growth	£200.00
5	- Continue to inspect embankment yearly to keep track of, identify potential issues - Continue vegetation management to prevent growth of undesirable vegetation on embankment - Infill identified low spots on crest with topsoil and lay down grass seed	£1,100.00
10	Continue yearly inspections and vegetation management	£2,500.00




	• If extensive damage has been incurred to embankment, reprofile bank and lay down grass seed • Repaint sheet piling • Repair any damage to gabion baskets	
15	• Continue yearly inspections and vegetation management • If extensive damage has been incurred to embankment, reprofile bank and lay down grass seed • Repair any damage to concrete apron and gabion baskets • Consider employing engineer to assess asset condition in detail to identify potential structural issues with embankment, employ relevant operative to repair damage	£9,600.00



CL22 – Embankment

Earth embankment with stone wall and sheet piling exposed faces and concrete berm. Crest height and embankment width reduce as earth landward face diminishes and crest changes to stone crest.



4.1.21 Comments

Minor vegetation growth within berm 1 and exposed face 2 with minor mortar loss. Uneven crest with some low spots but well vegetated. Berm 2 and channel side in good condition with minor cosmetic defects to sheet piling. Landward face and exposed face 1 are well vegetated but uneven. Landward face 2 around corner and has minor vegetation growing through stone and minor mortar loss.

Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	- Inspect embankment annually and infill any identified low spots on crest with topsoil and lay down grass seed - Repair mortar loss and remove vegetation growing through - Manage vegetation to avoid undesirable vegetation growth	£200.00
5	- Continue to inspect embankment yearly to keep track of, identify potential issues - Continue vegetation management to prevent the growth of undesirable vegetation on embankment - Conduct small repairs on brick and mortar loss - Infill identified low spots on crest with topsoil and lay down grass seed	£1,600.00
10	Continue yearly inspections and vegetation management	£3,400.00




	• If extensive damage has been incurred to embankment, reprofile bank and lay down grass seed • Continue with small repairs of brick and mortar loss • Repaint sheet piling • If extensive damage has been incurred to wall, rebuild wall	
15	• Continue yearly inspections and vegetation management • If extensive damage has been incurred to embankment, reprofile bank and lay down grass seed • Repair any damage to concrete apron and wall • Consider employing engineer to assess asset condition in detail to identify potential structural issues with embankment, employ relevant operative to repair damage	£9,600.00



CL23 – Outfall

Flapped outfall with unknown diameter located behind metal barrier which obstructs view of outfall.



4.1.22 Comments

Minor corrosion to barrier. Unable to see headwall and pipe due to high water level and barrier around.


Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	- Investigate dimensions and condition of outfall - Carry out CCTV inspection to assess pipe condition - Conduct annual visual asset inspections to assess the condition of the asset	£600.00
5	- Continue to inspect outfall yearly, including CCTV inspections of pipe every 5 years - Monitor stability of metal barrier and replace if necessary	£3,500.00
10	- Continue yearly inspections of the outfall - Manage any vegetation growth which could damage asset	£6,900.00
15	- Continue yearly inspections of the outfall and manage vegetation growth - If there has been any serious structural damage to the outfall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£23,700.00



CL24 – Wall

High stone wall with capping stones located off right bank and going away from main channel towards village.



4.1.23 Comments

Minor vegetation growth through crest. Minor mortar loss on exposed face and a couple of holes on both faces, not whole way though. Few bricks missing for drainage

Grade = 3, Fair

Years	Recommendations	Cumulative Cost (£)
1	- Repair holes in wall and remove vegetation - Conduct visual asset inspections annually - Maintain surrounding vegetation to avoid wall incurring structural damage	£200.00
5	- Continue to inspect the wall yearly to keep track of and identify potential issues - Conduct small repairs to brick and mortar loss and manage surrounding vegetation	£1,100.00
10	Carry out repointing of wall and continue with small repairs to brickwork and management of surrounding vegetation	£2,200.00
15	If there has been any serious structural damage to the wall over time such as cracking or movement, employ an engineer to investigate. If investigations have found structural damage, employ the relevant operative to repair the damage	£9,200.00



5.0 Summary Costs of Repair and Maintenance

TABLE 2: TOTAL COST

Asset	Immediate	1 Year	5 Years	10 Years	15 Years
CL1	£400.00	£600.00	£3,500.00	£12,500.00	£16,600.00
CL2		£600.00	£3,100.00	£13,200.00	£21,500.00
CL3	£1,900.00	£200.00	£1,000.00	£2,100.00	£10,100.00
CL4		£600.00	£3,500.00	£6,900.00	£17,400.00
CL5		£600.00	£3,500.00	£6,900.00	£17,400.00
CL6	£5,000.00	£200.00	£1,000.00	£2,100.00	£11,000.00
CL7		£600.00	£3,500.00	£6,900.00	£14,800.00
CL8		£600.00	£3,500.00	£6,900.00	£14,800.00
CL9		£600.00	£3,500.00	£6,900.00	£14,800.00
CL10		£600.00	£3,500.00	£6,900.00	£14,800.00
CL11		£600.00	£3,500.00	£6,900.00	£14,800.00
CL12		£600.00	£3,500.00	£6,900.00	£14,800.00
CL13		£700.00	£5,500.00	£17,900.00	£34,200.00
CL14		£600.00	£1,100.00	£2,200.00	£12,000.00
CL15		£200.00	£1,200.00	£2,400.00	£7,700.00
CL16		£200.00	£1,000.00	£2,000.00	£5,900.00
CL17		£200.00	£1,200.00	£4,800.00	£8,200.00
CL18		£7,200.00	£33,400.00	£90,100.00	£166,600.00
CL19		£600.00	£3,500.00	£6,900.00	£17,400.00
CL20		£600.00	£3,500.00	£6,900.00	£17,400.00
CL21		£200.00	£1,100.00	£2,500.00	£9,600.00
CL22		£200.00	£1,600.00	£3,400.00	£9,600.00
CL23		£600.00	£3,500.00	£6,900.00	£23,700.00
CL24		£200.00	£1,100.00	£2,200.00	£9,200.00
Total	£7,300.00	£18,000.00	£94,000.00	£233,700.00	£504,300.00



6.0 Summary

Overall, three of the flood assets are in poor condition, two are walls which will require reconstruction, and the first of the embankments requires the installation of a none return valve to retain its flood defence function. There are six outfalls in good condition and the remaining fourteen flood assets are in fair condition. All assets are no longer inspected by the Environment Agency and have a limited flood protection function, the capacity of the channel itself and the lower land on the opposite bank provides some protection to the site.

The associated costs from immediate action to 15 years ahead involve visual asset inspections which will allow the condition of each asset to be assessed in order to ensure the assets remain in good working order. Vegetation management is also a very consistent cost for almost all assets since root penetration and undesirable vegetation can destabilise assets which could cause them to fail. Mortar repair is a minor but regular maintenance requirement for all defences and structures containing brickwork to ensure internal degradation to brick structures is reduced.

Larger costs which may be required after a longer period of time include the replacement of sheet piling, bank reprofiling and repointing of walls. These costs would be necessary to ensure the assets remain stable.

The recommendations made in Section 4 emphasise monitoring and management to maintain assets to allow them to reach or maintain a condition grade of 3 - 'Fair'. Monitoring and management makes up most of the 5 and 10 year costings outlined in Table 2, including yearly inspections, vegetation management, and minor repair work where required.

For the 15-year period, more intrusive, structural recommendations have been made to maintain assets to achieve condition grade 3 - 'Fair'. These recommendations make assumptions that the assets will degrade over time, and that erosion of the channel side will continue. Investigations by engineers will be required to determine any further work required at the time.



Appendix A: Asset inspection logs

Asset inspection logs including photos are available to download as PDF documents.



Asset ID	CL1	Frequency		 RESILIENCE & FLOOD RISK			
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Defence	Asset Type - Subtype	Embankment				
Asset Location	Cleator						
Description	Near to Millers Walk, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Crest	Earth				9	3
2	Landward Face	Earth				7	3
3	Exposed Face	Earth				7	3
4	Channel Side	Earth				5	3
5	Berm	Earth				5	2
6							
7							
8							
9							
10							
11							
Calculated	3	Worst		Override			
Override Reason							
Comments	Variant weighting used for crest as <4m wide. Drainage pipe running through entire width of embankment, low spots, some animal holes and rutting on crest, Landward face and exposed face have some holes and uneven slopes but are well vegetated. Undermining, minor erosion and light foreign objects present on channel side but currently stable.						
Recommendations	Infill low spots on crest, remove drainage pipe from embankment and consider pest control.						



Asset ID		Frequency					
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Channel	Asset Type - Subtype	Natural High Ground				
Asset Location	Cleator						
Description	Near to Millers Walk, Cleator						
Current Asset Condition	CL2	Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	High ground	Earth				2	2
2	Channel Side	Earth				5	3
3							
4							
5							
6							
7							
8							
9							
10							
11							
Calculated	3	Worst		Override			
Override Reason							
Comments	Significant undermining, erosion and presence of light foreign objects on channel side. High ground in good condition.						
Recommendations	Monitor erosion, consider installing erosion protection layer to channel side.						



Asset ID	CL3	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
							
Asset Inspector	Alexandra Mackaness						
Asset Name	Defence	Asset Type - Subtype	Wall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Crest	Stone				7	3
2	Landward Face	Stone				9	4
3	Exposed Face	Stone				9	4
4	Channel Side	Earth				5	3
5	Berm	Earth				5	2
6							
7							
8							
9							
10							
11							
Calculated	3	Worst		Override	4		
Override Reason	Critical element has lower grading						
Comments	Variant weightings used for both faces as no revetments. Significant mortar loss to crest, holes through wall, bulging of wall where light foreign objects are growing in front on wall, distorting its shape and minor erosion to channel side.						
Recommendations	Rebuild wall and remove trees in front of wall.						



Asset ID	CL4	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Structure	Asset Type - Subtype	Outfall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Frame	Metal				7	2
2	Flap valve	Metal				9	2
3	Pipe	Unknown			X	9	3
4	Apron	Concrete				5	2
5	Downstream headwall	Stone and concrete				8	3
6							
7							
8							
9							
10							
11							
Calculated	2	Worst		Override	3		
Override Reason	Critical element has lower grading						
Comments	Vegetation around headwall. Unable to see through pipe and no CCTV footage available.						
Recommendations	Conduct a CCTV survey to inspect pipe and remove vegetation around headwall.						



Asset ID	CL5	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Structure	Asset Type - Subtype	Outfall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Frame	Metal				7	2
2	Flap valve	Metal				9	2
3	Pipe	Unknown			X	9	3
4	Downstream headwall	Stone and concrete				8	2
5							
6							
7							
8							
9							
10							
11							
Calculated	2	Worst		Override	3		
Override Reason	Critical element has lower grading						
Comments	Outfall in good condition, very minor corrosion present on frame and flap valve. Unable to see through pipe and no CCTV footage available.						
Recommendations	Conduct a CCTV survey to inspect pipe.						



Asset ID	CL6	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
							
Asset Inspector	Alexandra Mackaness						
Asset Name	Defence	Asset Type - Subtype	Wall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Crest	Stone				7	4
2	Landward Face	Stone				9	4
3	Exposed Face	Stone				9	4
4	Channel Side	Earth				5	3
5	Berm	Earth				5	3
6							
7							
8							
9							
10							
11							
Calculated	4	Worst		Override			
Override Reason							
Comments	Heavy foreign objects growing towards channel on berm and channel side and undermining on channel side causing channel side to be unstable. Ivy growth on wall, heavy foreign objects growing close to wall causing bulging to wall and capping stones lost from crest halfway across wall.						
Recommendations	Rebuild wall, remove unstable trees and remove trees next to wall.						



Asset ID	CL7	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Structure	Asset Type - Subtype	Outfall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Frame	Metal				7	2
2	Flap valve	Metal				9	2
3	Pipe	Unknown				9	2
4	Downstream headwall	Stone and concrete				8	3
5							
6							
7							
8							
9							
10							
11							
Calculated	2	Worst		Override			
Override Reason							
Comments	No signs of corrosion to flap valve or frame, pipe has minor leaf debris but no blockages or damage. Downstream headwall has some cracks, vegetation growth and mortar loss.						
Recommendations	Continue with ongoing vegetation maintenance.						



Asset ID	CL8	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Structure	Asset Type - Subtype	Outfall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Frame	Metal				7	2
2	Flap valve	Metal				9	2
3	Pipe	Unknown				9	2
4	Downstream headwall	Stone and concrete				8	3
5							
6							
7							
8							
9							
10							
11							
Calculated	2	Worst		Override			
Override Reason							
Comments	No signs of corrosion to flap valve or frame, pipe has minor leaf debris but no blockages or damage. Minor crack to downstream headwall, vegetation growth and mortar loss.						
Recommendations	Continue with ongoing vegetation maintenance.						



Asset ID	CL9	Frequency		 RESILIENCE & FLOOD RISK			
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Structure	Asset Type - Subtype	Outfall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Frame	Metal				7	3
2	Flap valve	Metal				9	2
3	Pipe	Unknown			X	9	2
4	Downstream headwall	Stone and concrete				8	3
5							
6							
7							
8							
9							
10							
11							
Calculated	2	Worst		Override			
Override Reason							
Comments	No corrosion to flap valve or frame. Cracks and mortar loss on headwall. Pipe has minor leaf debris but no blockages or damage.						
Recommendations	Remove vegetation and continue with vegetation maintenance.						



Asset ID	CL10	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Structure	Asset Type - Subtype		Outfall			
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Frame	Metal				7	3
2	Flap valve	Metal				9	2
3	Pipe	Unknown			X	9	2
4	Downstream headwall	Stone and concrete				8	3
5							
6							
7							
8							
9							
10							
11							
Calculated	2	Worst		Override			
Override Reason							
Comments	Ivy growth around frame and headwall. No corrosion to flap valve. Cracks and vegetation growth on headwall. Pipe has minor leaf debris but no blockages or damage.						
Recommendations	Remove vegetation and continue with vegetation maintenance.						



Asset ID	CL11	Frequency						
Latest Assessment Date	28/01/2022	Due Date						
Asset Inspector	Alexandra Mackaness							
Asset Name	Structure	Asset Type - Subtype	Outfall					
Asset Location	Cleator							
Description	Hilden Road, Cleator							
Current Asset Condition		Target condition	3					
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition	
1	Frame	Metal				7	3	
2	Flap valve	Metal				9	2	
3	Pipe	Unknown			X	9	2	
4	Downstream headwall	Stone and concrete				8	3	
5								
6								
7								
8								
9								
10								
11								
Calculated	2	Worst		Override				
Override Reason								
Comments	Ivy growth around frame and headwall. No corrosion to flap valve. Minor cracks and vegetation growth on headwall. Pipe has vegetation debris but no blockages or damage.							
Recommendations	Remove vegetation and continue with vegetation maintenance.							



Asset ID	CL12	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Structure	Asset Type - Subtype	Outfall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Frame	Metal				7	3
2	Flap valve	Metal				9	2
3	Pipe	Unknown			X	9	2
4	Downstream headwall	Stone and concrete				8	3
5							
6							
7							
8							
9							
10							
11							
Calculated	2	Worst		Override			
Override Reason							
Comments	No corrosion to flap valve or frame. Minor cracks, mortar loss and minor vegetation growth on headwall. Pipe has minor leaf debris but no blockages or damage.						
Recommendations	Remove vegetation and continue with vegetation maintenance.						



Asset ID	CL13	Frequency						
Latest Assessment Date	28/01/2022	Due Date						
Asset Inspector	Alexandra Mackaness							
Asset Name	Channel	Asset Type - Subtype	Natural High Ground					
Asset Location	Cleator							
Description	Near to Millers Walk, Cleator							
Current Asset Condition		Target condition	3					
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition	
1	High ground	Tarmac				2	2	
2	Channel Side	Earth				5	3	
3								
4								
5								
6								
7								
8								
9								
10								
11								
Calculated	3	Worst		Override				
Override Reason								
Comments	Significant undermining, erosion and presence of light foreign objects on channel side. High ground in good condition.							
Recommendations	Monitor erosion, consider installing erosion protection layer to channel side.							



Asset ID	CL14	Frequency						
Latest Assessment Date	28/01/2022	Due Date						
Asset Inspector	Alexandra Mackaness							
Asset Name	Channel	Asset Type - Subtype	Natural High Ground					
Asset Location	Cleator							
Description	Near to Millers Walk, Cleator							
Current Asset Condition		Target condition	3					
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition	
1	High ground	Tarmac				2	2	
2	Channel Side	Earth				5	3	
3								
4								
5								
6								
7								
8								
9								
10								
11								
Calculated	3	Worst		Override				
Override Reason								
Comments	Light foreign objects and ivy growing in front of and on top of channel side wall. High ground is road in good condition. Heavy foreign object upstream with roots growing into channel side brickwork.							
Recommendations	Remove trees on top of and in front of channel side brickwork. Remove ivy.							



Asset ID	CL15	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
							
Asset Inspector	Alexandra Mackaness						
Asset Name	Defence	Asset Type - Subtype	Wall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Crest	Stone				7	3
2	Landward Face	Stone				9	3
3	Exposed Face	Stone				9	3
4	Channel Side	Earth				5	3
5	Berm	Earth				5	3
6							
7							
8							
9							
10							
11							
Calculated	3	Worst		Override			
Override Reason							
Comments	Several heavy foreign objects on berm and channel side. Severe mortar loss in landward face, exposed face difficult to inspect but wall covered in ivy and some tree roots and growing through it. Crest is uneven where ivy has grown around it.						
Recommendations	Rebuild wall, remove ivy and remove trees growing into wall.						



Asset ID	CL16	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
							
Asset Inspector	Alexandra Mackaness						
Asset Name	Defence	Asset Type - Subtype	Wall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Crest	Stone				7	4
2	Landward Face	Stone				9	2
3	Exposed Face	Stone				9	3
4	Channel Side	Earth				5	4
5							
6							
7							
8							
9							
10							
11							
Calculated	3	Worst		Override			
Override Reason							
Comments	Extensive ivy growth, channel side wall is walling down with severe brick loss and root penetration. Heavy foreign objects growing on channel side causing brick displacement and loss. Crest is uneven due to brick loss but landward face is made from concrete slabs in good condition.						
Recommendations	Rebuild wall and remove heavy foreign objects.						



Asset ID	CL17	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
							
Asset Inspector	Alexandra Mackaness						
Asset Name	Channel	Asset Type - Subtype	Natural High Ground				
Asset Location	Cleator						
Description	Near to Millers Walk, Cleator						
Current Asset Condition	3	Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	High ground	Tarmac				2	2
2	Channel Side	Earth				5	3
3							
4							
5							
6							
7							
8							
9							
10							
11							
Calculated	3	Worst		Override			
Override Reason							
Comments	Heavy foreign objects on channel side leaning towards channel. Building <3m from channel on high ground.						
Recommendations	Continue with vegetation maintenance and monitor tree growth.						



Asset ID	CL18	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Defence	Asset Type - Subtype	Embankment				
Asset Location	Cleator						
Description	Near to Millers Walk, Cleator						
Current Asset Condition	4	Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Crest	Earth				9	3
2	Landward Face	Earth				9	3
3	Exposed Face	Earth				9	3
4	Channel Side	Earth				7	4
5							
6							
7							
8							
9							
10							
11							
Calculated	3	Worst		Override			
Override Reason							
Comments	Low points and rutting in crest but well vegetated. Variant used for exposed face due to steepness. Exposed and landward faces have isolated bare patches. Telegraph pole behind embankment but embankment build around it. Severe undermining of channel side around heavy foreign objects with extensive root exposure.						
Recommendations	Remove unstable trees on channel side, infill low spots on crest and seed bare patches.						



Asset ID	CL19	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
							
Asset Inspector	Alexandra Mackaness						
Asset Name	Structure	Asset Type - Subtype	Outfall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Pipe	Unknown			X	9	3
2	Apron	Concrete				5	3
3	Downstream headwall	Stone and concrete				8	3
4							
5							
6							
7							
8							
9							
10							
11							
Calculated	3	Worst		Override			
Override Reason							
Comments	Drainage pipe halfway between wall and building on high ground. Unable to see through pipe and no CCTV footage available. Vegetation around headwall and at base of pipe.						
Recommendations	Remove vegetation and provide ongoing vegetation maintenance. Conduct CCTV inspection of pipe.						



Asset ID	CL20	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Structure	Asset Type - Subtype	Outfall				
Asset Location	Cleator						
Description	Hilden Road, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Pipe	Unknown			X	9	3
2	Downstream headwall	Stone and concrete				8	4
3							
4							
5							
6							
7							
8							
9							
10							
11							
Calculated	3	Worst		Override			
Override Reason							
Comments	Downstream headwall in pieces. Unable to see through pipe and no CCTV footage available.						
Recommendations	Rebuild headwall and conduct CCTV inspection of pipe.						



Asset ID	CL21	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Defence	Asset Type - Subtype	Embankment				
Asset Location	Cleator						
Description	Near to Millers Walk, Cleator						
Current Asset Condition	3	Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Crest	Earth				9	3
2	Landward Face	Earth				7	2
3	Exposed Face 1	Earth				7	2
4	Berm 1	Gabions				5	3
5	Exposed Face 2	Gabions				7	3
6	Berm 2	Concrete				5	2
7	Channel Side	Sheet piling				5	2
8							
9							
10							
11							
Calculated	2	Worst		Override	3		
Override Reason	Critical element has worse condition grade						
Comments	Berm 2 and channel side in good condition with minor cosmetic defects to sheet piles. Vegetation growth through gabion baskets with a few broken wires but no gabion displacement. Uneven ground on exposed face 1 and landward face but well vegetated. Rutting and low spots in isolated places on crest. Variants used on crest as less than 4m wide and landward face due to steepness.						
Recommendations	Remove vegetation in gabions and repair wires. Infill low spots on crest.						



Asset ID	CL22	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
							
Asset Inspector	Alexandra Mackaness						
Asset Name	Defence	Asset Type - Subtype	Embankment				
Asset Location	Cleator						
Description	Between Mill Street and Brookside, Cleator						
Current Asset Condition	3	Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Crest	Earth				9	3
2	Landward Face	Earth				7	2
3	Exposed Face 1	Earth				7	2
4	Berm 1	Stone				5	3
5	Exposed Face 2	Stone				7	2
6	Berm 2	Concrete				5	2
7	Channel Side	Sheet piling				5	2
8	Landward face 2	Stone				7	2
9							
10							
11							
Calculated	2	Worst		Override	3		
Override Reason	Critical element has worse condition grade						
Comments	Minor vegetation growth within berm 1 and exposed face 2 with minor mortar loss. Uneven crest with some low spots but well vegetated. Berm 2 and channel side in good condition with minor cosmetic defects to sheet piling. Landward face and exposed face 1 are well vegetated but uneven. Landward face 2 around corner and has minor vegetation growing through stone and minor mortar loss.						
Recommendations	Monitor vegetation growth in wall and infill low spots in crest.						



Asset ID	CL23	Frequency							
Latest Assessment Date	28/01/2022	Due Date							
									
Asset Inspector	Alexandra Mackaness								
Asset Name	Structure	Asset Type - Subtype						Outfall	
Asset Location	Cleator								
Description	Between Mill Street and Brookside, Cleator								
Current Asset Condition		Target condition	3						
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition		
1	Downstream headwall	Stone and concrete			X	8	3		
2	Pipe	Unknown			X	9	3		
3	Barrier	Metal				2	3		
4									
5									
6									
7									
8									
9									
10									
11									
Calculated	3	Worst		Override					
Override Reason									
Comments	Minor corrosion to barrier. Unable to see headwall and pipe due to high water level and barrier around.								
Recommendations	Conduct CCTV inspection for pipe and headwall.								



Asset ID	CL24	Frequency					
Latest Assessment Date	28/01/2022	Due Date					
Asset Inspector	Alexandra Mackaness						
Asset Name	Defence	Asset Type - Subtype	Wall				
Asset Location	Cleator						
Description	Brookside, Cleator						
Current Asset Condition		Target condition	3				
Element Sequence	Element Type	Material	Photo ref	Notes	ENI	Weighting	Condition
1	Crest	Stone				7	3
2	Landward Face	Stone				9	3
3	Exposed Face	Stone				9	3
4							
5							
6							
7							
8							
9							
10							
11							
Calculated	3	Worst		Override			
Override Reason							
Comments	Minor vegetation growth through crest. Minor mortar loss on exposed face and a couple of holes on both faces, not whole way though. Few bricks missing for drainage.						
Recommendations	Repair holes in wall and remove vegetation.						





APPENDIX H: UNITED UTILITIES GIS


Scale Approx 1: 1249

MK


© The plan is based upon the Ordnance Survey Map with the sanction of the Controller of H.M Stationery Office. Crown and United Utilities copyrights are reserved. Unauthorised reproduction will infringe these copyrights.

————— Public Sewer
 - - - - - Highway Drain
 - - - - - Private Sewer
 - - - - - Pumping Main

Approximate Scale 1: 1249



This plot has been issued to ATKINST of Atkins Stats on 08-Jul-13 **NOT FOR RESALE OR NON-APPROVED USE**



Extract from Map from Public Sewers

The position of underground apparatus shown on this plan is approximate only and is given in accordance with the best informatin currently available.

The actual postions may be different from those shown on the plan and private pipes, sewers or drains are not recorded.

United Utilities will not accept any liability for any damage caused by the actual positions being different from those shown.

© The plan is based upon the Ordnance Survey Map with the sanction of the Controller of H.M Stationery Office. Crown and United Utilities copyrights are reserved. Unauthorised reproduction will infringe these copyrights.

Red or Brown - Foul Sewers
Blue - Surface Water Sewers


- Public Sewer
- Highway Drain
- Private Sewer
- Pumping Main

DO NOT SCALE

Approximate Scale 1: 1249



This plot has been issued to ATKINST of Atkins Stats on 08-Jul-13 **NOT FOR RESALE OR NON-APPROVED USE**



Extract from Map from Public Sewers

The position of underground apparatus shown on this plan is approximate only and is given in accordance with the best informatin currently available.

The actual postions may be different from those shown on the plan and private pipes, sewers or drains are not recorded.

United Utilities will not accept any liability for any damage caused by the actual positions being different from those shown.

© The plan is based upon the Ordnance Survey Map with the sanction of the Controller of H.M Stationery Office. Crown and United Utilities copyrights are reserved. Unauthorised reproduction will infringe these copyrights.

Red or Brown - Foul Sewers
Blue - Surface Water Sewers

- Public Sewer
- Highway Drain
- Private Sewer
- Pumping Main

DO NOT SCALE


Approximate Scale 1: 1249



Scale Approx 1: 1249



This plot has been issued to ATKINST of Atkins Stats on 08-Jul-13 **NOT FOR RESALE OR NON-APPROVED USE**



ATKINS CHECKED

MK

Extract from Map of Public Water Mains

The position of underground apparatus shown on this plan is approximate only and is given in accordance with the best informatin currently available.

The actual postions may be different from those shown on the plan and private pipes, sewers or drains are not recorded.

United Utilities will not accept any liability for any damage caused by the actual positions being different from those shown.

© The plan is based upon the Ordnance Survey Map with the sanction of the Controller of H.M Stationery Office. Crown and United Utilities copyrights are reserved. Unauthorised reproduction will infringe these copyrights.

Blue - Distribution Mains
Red or Mauve - Trunk Mains
Dark Green - Non Potable Mains


---x---x---x--- Disused Mains
(These may still be live!)

DO NOT SCALE

Approximate Scale 1: 1249



This plot has been issued to ATKINST of Atkins Stats on 08-Jul-13 **NOT FOR RESALE OR NON-APPROVED USE**



Extract from Map of Public Water Mains

The position of underground apparatus shown on this plan is approximate only and is given in accordance with the best information currently available.

The actual positions may be different from those shown on the plan and private pipes, sewers or drains are not recorded.

United Utilities will not accept any liability for any damage caused by the actual positions being different from those shown.

© The plan is based upon the Ordnance Survey Map with the sanction of the Controller of H.M Stationery Office. Crown and United Utilities copyrights are reserved. Unauthorised reproduction will infringe these copyrights.

Blue - Distribution Mains
Red or Mauve - Trunk Mains
Dark Green - Non Potable Mains

---x---x---x--- Disused Mains
(These may still be live!)

DO NOT SCALE

Approximate Scale 1: 1249




This plot has been issued to ATKINST of Atkins Stats on 08-Jul-13 **NOT FOR RESALE OR NON-APPROVED USE**

Centre: 302087,513706

Date:08-07-2013

Scale Approx 1: 1249



Extract from Map of Public Water Mains

The position of underground apparatus shown on this plan is approximate only and is given in accordance with the best information currently available.

The actual positions may be different from those shown on the plan and private pipes, sewers or drains are not recorded.

United Utilities will not accept any liability for any damage caused by the actual positions being different from those shown.

© The plan is based upon the Ordnance Survey Map with the sanction of the Controller of H.M Stationery Office. Crown and United Utilities copyrights are reserved. Unauthorised reproduction will infringe these copyrights.

Blue - Distribution Mains
Red or Mauve - Trunk Mains
Dark Green - Non Potable Mains

---x---x---x--- Disused Mains
(These may still be live!)

DO NOT SCALE

Approximate Scale 1: 1249




This plot has been issued to ATKINST of Atkins Stats on 08-Jul-13 **NOT FOR RESALE OR NON-APPROVED USE**

Centre: 301832,513701

Date:08-07-2013

Scale Approx 1: 1249



Extract from Map of Public Water Mains

The position of underground apparatus shown on this plan is approximate only and is given in accordance with the best information currently available.

The actual positions may be different from those shown on the plan and private pipes, sewers or drains are not recorded.

United Utilities will not accept any liability for any damage caused by the actual positions being different from those shown.

© The plan is based upon the Ordnance Survey Map with the sanction of the Controller of H.M Stationery Office. Crown and United Utilities copyrights are reserved. Unauthorised reproduction will infringe these copyrights.

Blue - Distribution Mains
Red or Mauve - Trunk Mains
Dark Green - Non Potable Mains

---x---x---x--- Disused Mains
(These may still be live!)

DO NOT SCALE

Approximate Scale 1: 1249





E-mail: info@rwo.group | Website: www.rwo.group | Telephone: 0330 0566900
 RwoAssociates |  RwoAssociates

