




PHOTOMONTAGE REPORT

HAILE MOOR MINE
EGREMONT
CUMBRIA
CA22 2PE

DATE: 22/11/24
VERSION: V1

Produced By





Title	Viewport Locations	Client	Produced By
Site Address	HAILE MOOR MINE EGREMONT CUMBRIA CA22 2PE		



Title	Existing View of Viewport 1	Client	Produced By
Easting	304122		
Northing	508979		
Direction	167°		
Distance	281m		



Title	Proposed View of Viewport 1	Client	Produced By
Easting	304122		
Northing	508979		
Direction	167°		
Distance	281m		



Title	Existing View of Viewport 2	Client	Produced By
Easting	303965		
Northing	508992		
Direction	141°		
Distance	356m		



Title	Proposed View of Viewport 2	Client	Produced By
Easting	303965		
Northing	508992		
Direction	141°		
Distance	356m		



Title	Existing View of Viewport 3	Client	Produced By
Easting	303388		
Northing	508708		
Direction	90°		
Distance	785m		



Title	Proposed View of Viewport 3	Client	Produced By
Easting	303388		
Northing	508708		
Direction	72°		
Distance	785m		