




Survey Report Dates	12 to 18 August 2019
Report Type	Daily 14 Bin Speed with summary report
Notes:	

Unit D Items Way
Engineered Retention Park
Culvert
CAD 457



NORTHWEST LINK
10077 FIVE OAKS CIRCLE, TACOMA, WA 98404

A.T.C. Site Visit & Check Schedule.

Road Name / No.	A5085				
Site Description	11419 Main Street Culvert				
Site ID	196-00044				
Nat. Grid Ref.	307 991 31 1885				
County Type	NORTH				
County No.	1303-B0066				
Time Installed	14 th July 2020				
Date Removed	21 st July 2020				

VISITS

Date	Data Removed	Battery Charged	Check Count	Tube Failed	Tube Replaced	Remarks
14/07/20						Tubes Installed
21/07/20	13670044-1436					Tubes Removed

Channel #1 = North East

Channel #2 = South West

Speed Limit 30

The site has been assessed as per the method statement and is deemed safe for installation.

Technicians Name: Jonathan Robinson

Northwest Link Traffic Data Company

Revision 1.2 March 2013

